

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1027

Michael O. Leavitt Governor Kathleen Clarke

Executive Director

Lowell P. Braxton

Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX Complete:	Exploration:
Inspection Date & Time:	
Date of Last Inspection:	

Mine Name: Gordon Creek 2, 7, and 8 County: Carbon Permit Number: Permit Number: Mountain Coal Company

Business Address: HC 35 Box 380, Helper, Utah 84526

Type of Mining Activity: Underground XXX Surface Prep. Plant Other

Company Official(s): Dan Guy

State Official(s): Joe Helfrich Federal Official(s): None

Weather Conditions: Clear, 75

Existing Acreage: Permitted 2286 Disturbed 20.3 Regraded Seeded

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.

Status: Active Reclamation XXX

- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	<u>COMMENTS</u>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	\Box	[X]	\Box
2.	SIGNS AND MARKERS	[X]	\Box	[X]	Ц
3.	TOPSOIL	[X]	\Box	[X]	\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS	П	\Box	\Box	\Box
	c. OTHER SEDIMENT CONTROL MEASURES	П	\Box		\Box
	d. WATER MONITORING		\Box	\Box	\Box
	e. EFFLUENT LIMITATIONS	П			\Box
5.	EXPLOSIVES	\Box	\Box	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		\Box	П	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		\Box		
8.	NONCOAL WASTE	\Box	\Box	\Box	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	\Box	\Box		
10.	SLIDES AND OTHER DAMAGE	\Box	\Box		
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box		П
12.	BACKFILLING AND GRADING	\Box	\Box		\Box
13.	REVEGETATION	\Box	\Box	Ц	П
14.	SUBSIDENCE CONTROL	\Box	\Box		П
15.	CESSATION OF OPERATIONS	П	\Box		П
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING		\Box		П
	b. DRAINAGE CONTROLS	\Box	П	П	Π̈́
17.	OTHER TRANSPORTATION FACILITIES	\Box	\Box	П	П
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	П	П	ĹΪ	Щ
	AVS CHECK (4th Quarter- April, May, June)	\Box	\Box	Ω	
	AIR QUALITY PERMIT	П	\Box	П	Ц
21.	BONDING & INSURANCE	П	\Box		Ш

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/016

DATE OF INSPECTION: 08/01/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

There is one amendment pending, #99C-2, revisions to the permit area. The review is scheduled for completion on August 10, 2001.

2. SIGNS AND MARKERS

New signs have been placed at the main access at the end of the county road.

3. TOPSOIL

Topsoil from the logging road above the reclaimed area continues to be transported to the flatter low gradient areas of the first side channel, (SD #6), and sediment pond. As the water in the pond recedes, the plume of sediment from the logging road is becoming visible. An estimation of the total capacity, (design storm and sediment), of the three-celled pond should be performed when the pond has dried out.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions are in good repair and functioning well. The lower 15-20' of SD #6, where it enters the main channel, has been cutting into the embankment. The remaining upstream portions of this side drainage are functioning quite well as tested by fall 2000 precipitation events and 2001 spring runoff. That portion of the channel from where the designed channel ends to the main channel has been armored. The armoring consisted of straw bale placement with several layers of rock. The newly formed reach of channel appeared to have reached its bottom point in most places. The armoring has provided a stable transport area for additional run-off as evidenced by a recent precipitation event.

Inspector's Signature: July United Date: August 9, 2001

Joseph C. Helfrich #1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas &

Mining.

sd

cc: James Fulton, OSM

Chris Hansen, Canyon Fuel Company Dan Guy, Blackhawk Engineering

Price Field office

 $O:\label{lem:compliance} O:\label{lem:compliance} O:\label{lem:compli$